

Classification: A
Billable to Telco: Yes _____ No X

APPARATUS AFFECTED: 35A and 35B Converter-Reader

PART AFFECTED: TP156656 Strap Assembly

REASON: To provide an insulating cover for the A. C. power terminals.

CHANGE: A TP321325 connector cover is added to the front panel assembly and slip fits over the TP114467 power connector plug. The TP156656 strap assembly attached to the ground terminal of the TP114467 power connector plug is replaced by TP327712 strap assembly.

PUBLICATION AFFECTED: See SUPPLEMENTAL INFORMATION.

IDENTIFICATION: The TP321325 connector cover is a cone shaped cover 1-7/8 inch long and is made of black rubber. The TP156656 strap assembly is equipped with two closed type terminals and is 2-3/4 inches long. The TP327712 strap assembly is equipped with two closed type terminals and is 7-inches long.

The TP327712 strap assembly (frame ground strap) and the two wire leads terminating at the power plug are inserted through a small hole in the funnel end of the cover.

INTERCHANGEABILITY: The TP156656 strap assembly cannot be used with the TP321325 connector cover.

PARTS AVAILABILITY: The TP321325 connector cover is available in limited quantities. The TP327712 strap assembly is available.

SUPPLEMENTAL INFORMATION: The BSP Section covering parts has not been published; therefore, this information can be issued as an Appendix to Section 570-101-701, Issue 3. The parts are illustrated in Teletype Bulletin 1192B, Pages 1-3 and 1-8, Original.

REFERENCES: None

TCN INDEX CLASSIFICATION: 35 AH 25