

Teletype Corporation
Chicago, Illinois, U.S.A.

EE-516
Issue 1
January, 1946

CHANGES AND ADDITIONS
TO PARTS BULLETINS

1019	Issue 1	1064	Issue 2	1109	Issue 1
1028	Issue 2	1072	Issue 2	1110	Issue 2
1030	Issue 2	1080	Issue 1	1114	Issue 1
1031	Issue 3	1082	Issue 2	1116	Issue 1
1035	Issue 1	1088	Issue 2	1117	Issue 2
1036	Issue 3	1094	Issue 2	1119	Issue 1
1037	Issue 4	1095	Issue 1	1120	Issue 1
1041	Issue 4	1100	Issue 2	1122	Issue 2
1048	Issue 2	1101	Issue 1	1125	Issue 1
1051	Issue 1	1104	Issue 1	1127	Issue 1
1063	Issue 2	1105	Issue 1		

Reference is made in the above parts bulletins to the 77911 and 70873 brush holder caps. These two parts originally differed in that one (77911) had a tapped hole for a #6-32 screw to secure the filter lead, and the other (70873) did not. The 70873 has recently been changed to include the tapped hole, thus making the two parts identical. The 77911 brush holder cap has been cancelled and on orders for such part the 70873 brush holder cap will be furnished.