CHANGES IN TELETYPE PARTS BULLETINS

1028B, Issue 2 1030B, Issue 2 1031B, Issue 3	1073B, Issue 1 1074B, Issue 2 1080B, Issue 1	1109B, Issue 1 1110B, Issue 2 1116B, Issue 1	1131B, Issue 1 1138B, Issue 1 1141B, Issue 1
1041B, Issue 4	1087B, Issue 2	1117B, Issue 2	1142B, Issue 1
1063B, Issue 2	1088B, Issue 2	1121B, Issue 1	1143B, Issue 3
1064B, Issue 2	1100B, Issue 2	1125B, Issue 1	1144B, Issue 1
1068B, Issue 1	1107B, Issue 1	1126B, Issue 1	1150B, Issue 1
1072B, Issue 2	1108B, Issue 2	1130B, Issue 1	1151B, Issue 1

This correction sheet has been revised to include only those bulletins pertinent to the subject matter.

To provide improved performance with respect to maintenance of friction clutches and the selector end of main shafts, the following graphite impregnated felt washers and wicks replace the standard felt washers and wicks as indicated below:

Old	Graphite			
Style	Description	Impregnated		
6861	Washer	122741		
72883	Washer	122743		
74085	Wash er	122744		
74800	Washer	122745		
76084	Washer	*76084	distribution.	
77019	Washer	122747		
105045	Wick	122752	41 pr 4775	
113952	Washer	122748	4	

*Retains Old Number.

The 91265 cam sleeve (holding magnet) has been replaced by a 122754 cam sleeve.

The 115232 cam sleeve for the sequential selector has been replaced by a 129674 cam sleeve.

NOTE: The new cam sleeves have a graphite loaded bushing.

New and old style parts are interchangeable.

Printed in U.S.A.