


FIG. 1

**NOTES:**

1. ALL UNITS MOUNTED ON TP-159373 MODIFICATION KIT WITH .216 - 24 W E SPL RHM SCREWS.



**28KSR TTY IN 28 TYPE CABINET**  
**UNATTENDED TWX SERVICE**  
**130C1 TTY SUB SET**