CHANGES IN BULLETIN 1031, ISSUE 3 PARTS - TYPE BAR TAPE PRINTER (MODEL 14)

PAGE 15

The illustrations on Page 15 include parts for a special unit using 2" tape. For standard units using 3/8" tape refer to Pages 1 and 2.

PAGE 23

The 80811 electrical end-of-line indicator mechanism (assem.) which includes the 80812 electric impulse counter (assem.) is no longer available. This mechanism has been replaced by the 89960 set of mechanical parts shown on Page 33 which becomes the standard end-of-line indicator.

Printed in U.S.A.