

CHANGES IN
BULLETIN 138 (ISSUE 5)
ADJUSTMENTS - TYPE BAR PAGE PRINTER MODEL 15
AND
BULLETIN 160, (ISSUE 1)
ADJUSTMENTS - TYPE BAR PAGE PRINTER MODEL 20

BULLETIN 138, Page 7
BULLETIN 160, Page 5

RIBBON REVERSE SHAFTS LINKS ADJUSTMENT

Change the requirement to read .015" to .050" instead to .015" to .040".

BULLETIN 138, Page 11
BULLETIN 160, Page 8

CARRIAGE SUPPORT AND PULL BAR BAIL PLUNGER ROLLERS ADJUSTMENT

Change the requirements to read, with a barely perceptible amount of end play, instead of without end play.

BULLETIN 138, Page 32
BULLETIN 160, Page 22

LINE FEED CHECK LEVER ADJUSTMENT

Change the requirement to read, not more than .008" end play, instead of not more than .004".

BULLETIN 138, Page 37
BULLETIN 160, Page 26

CARRIAGE RETURN LOCK BAR LATCH ECCENTRIC SCREW ADJUSTMENT

Change the requirement in this adjustment to read .006" to .020" instead of .006" to .015".

Change corresponding figures accordingly.

* * * * *