




LINE CIRCUIT CLASS A



POWER CIRCUIT



- NOTES:**
1. FOR WIRING OF WC 9100-C SEE DWG. 232623
 2. ON WIRING DIAGRAM, C TERM SHOWN AS TS3, R TERM SHOWN AS TS, F TERM SHOWN AS KS.
 3. NORMALLY LOCATED IN STUENT BOX SLOT 28
 4. THIS WIRE IS IN WC 9100-A ONLY. FOR WIRING OF WC 9100-A SEE DWG. 174234.
 5. THESE WIRES ARE IN WC 9100-B AND WC 9100-C ONLY. FOR WIRING OF WC 9100-B AND WC 9100-C SEE DWG. 232623.
 6. THIS FUSE IS IN WC 9100-C ONLY.
 7. SIGNAL LINE BREAK SWITCH. WHEN USED, REMOVE STRAP BETWEEN C5 & C6.

REVISED	B. OCT 14, 1951
SCHEMATIC REVISION AND ADDITION OF 55V. A.C. COPYRIGHT SYSTEM APPROVED DWG.	
C. JUNE 5, 1961	NOTES 4, 5, 6 & 7 APPROVED
7/17/65	FILE CHANGE
DR. C. K. PRIN	APPROVED

FINISH:		NEXT ASST.	
MATERIAL:		USED ON	
TOLERANCE		SCALE	
UNLESS OTHERWISE SPECIFIED		INCHES	
DECIMAL		FRACTIONS	
ANGULAR		DRAWN	
BET. HOLES		TMS	
APD.		H. J.	
PRE		H. J.	
DATE		ISSUE	
184625-7		DRAWING NUMBER	
WESTERN UNION			
SWITCHING SYSTEM			
MODEL 28 TELEPRINTER			
WITH WIRING CABINET			
* 9100-A, B, C			
SCHEMATIC			